UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,938,989 B2 APPLICATION NO.: 09/835711

Page 1 of 1

DATED

: September 6, 2005

INVENTOR(S) : Kia Silverbrook

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 48, claim 1, lines 10-14 should read:

at least one double-sided tape automated bonded (TAB) film configured to connect a plurality of said power supply points to said at least one power busbar and a plurality of said ground supply points to said at least one ground busbar,

Signed and Sealed this

Nineteenth Day of August, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office